

480 volt 3 phase 6 lead motor wiring diagram

Decoding the 480 Volt 3 Phase 6 Lead Motor Wiring Diagram: Challenges, Opportunities, and Best Practices

Author: Dr. Anya Sharma, P.Eng., PMP. Dr. Sharma is a Professor of Electrical Engineering at the University of Alberta and a licensed Professional Engineer with over 15 years of experience in industrial motor control and power systems. She holds a PhD in Electrical Engineering and is a certified Project Management Professional (PMP).

Keyword: 480 volt 3 phase 6 lead motor wiring diagram

Abstract: This article provides a comprehensive guide to understanding and utilizing the 480 volt 3 phase 6 lead motor wiring diagram. We will explore the intricacies of this common industrial configuration, highlighting the potential challenges associated with its implementation and the opportunities for optimized performance and safety. The article will delve into various wiring configurations, troubleshooting techniques, and best practices for ensuring efficient and reliable operation.

Introduction: Navigating the Complexity of the 480 Volt 3 Phase 6 Lead Motor Wiring Diagram

The 480 volt 3 phase 6 lead motor wiring diagram is a cornerstone of industrial electrical systems. Understanding this diagram is crucial for electricians, technicians, and engineers involved in the installation, maintenance, and troubleshooting of three-phase motors. However, the apparent complexity of the six leads can be daunting, leading to potential safety hazards and operational inefficiencies if not properly understood. This article aims to demystify the 480 volt 3 phase 6 lead motor wiring diagram, outlining the challenges and opportunities presented by this prevalent configuration.

Understanding the Six Leads: Wye (Y) and Delta (Δ) Connections

The six leads emanating from a three-phase motor correspond to the three windings within the motor. Each winding has two leads, allowing for both Wye (Y) and Delta (Δ) configurations. The choice between these configurations affects the motor's voltage and current characteristics.

Wye (Y) Connection: In a Wye connection, one lead from each winding is joined together at a common neutral point. The other three leads are connected to the three-phase power supply. This connection provides a higher line-to-neutral voltage and lower line current compared to a Delta connection. The 480 volt 3 phase 6 lead motor wiring diagram for a Wye connection shows a clear connection of the

three common points.

Delta (Δ) Connection: In a Delta connection, the windings are connected in a closed loop, with no common neutral point. This configuration results in a lower line-to-neutral voltage but a higher line current compared to a Wye connection. A 480 volt 3 phase 6 lead motor wiring diagram for a Delta connection illustrates this closed-loop arrangement.

Understanding the difference between these connections is paramount for properly interpreting the 480 volt 3 phase 6 lead motor wiring diagram and ensuring correct voltage application to avoid damage. Incorrect connections can lead to motor burnout, necessitating costly repairs and downtime.

Challenges in Working with the 480 Volt 3 Phase 6 Lead Motor Wiring Diagram

Several challenges are inherent in working with a 480 volt 3 phase 6 lead motor wiring diagram:

Incorrect Wiring: Misinterpreting the diagram can lead to incorrect wiring, resulting in motor damage or safety hazards. The high voltage involved necessitates meticulous attention to detail.

Phase Rotation: Incorrect phase rotation can cause the motor to run in reverse or experience significant torque imbalances, potentially damaging the motor or connected machinery. The 480 volt 3 phase 6 lead motor wiring diagram must be carefully examined to ensure correct phase sequencing.

Troubleshooting: Identifying faults in a six-lead motor can be more complex than in a simpler configuration. Systematic troubleshooting methods and a thorough understanding of the 480 volt 3 phase 6 lead motor wiring diagram are essential.

Safety Concerns: Working with high-voltage systems inherently involves significant safety risks. Following proper lockout/tagout procedures and employing appropriate personal protective equipment (PPE) are non-negotiable.

Opportunities and Best Practices

Despite the challenges, working with the 480 volt 3 phase 6 lead motor wiring diagram presents numerous opportunities:

Flexibility: The dual configurations (Wye and Delta) offer flexibility in adapting the motor to different voltage and current requirements.

Efficiency: Choosing the optimal connection (Wye or Delta) can improve motor efficiency and reduce energy consumption.

Improved Performance: Proper wiring and configuration can enhance motor performance, ensuring optimal torque and speed control.

Reduced Downtime: Proactive maintenance, thorough understanding of the 480 volt 3 phase 6 lead motor wiring diagram, and effective troubleshooting minimize downtime caused by motor failures.

Best practices include:

Always verify the motor's nameplate data: This data is crucial for determining the correct voltage, current, and connection type.

Use a reliable wiring diagram: Ensure the diagram is accurate and matches the motor's specifications.

Employ a multimeter to verify connections: This step is critical for ensuring correct phase rotation and voltage levels.

Implement a robust preventative maintenance schedule: Regular inspections and testing can prevent catastrophic failures.

Consult qualified professionals: When in doubt, seek the advice of experienced electricians or engineers.

Troubleshooting Common Issues with 480 Volt 3 Phase 6 Lead Motors

Identifying and resolving problems with 480 volt 3 phase 6 lead motors requires a methodical approach. Common issues include:

Motor Failure to Start: Check power supply, wiring connections, fuses, overload relays, and motor windings.

Overheating: Inspect for faulty bearings, inadequate ventilation, overload conditions, or incorrect wiring.

Unusual Noises: Examine bearings, couplings, and the motor itself for signs of wear or damage.

Reduced Torque: Consider load imbalances, low voltage, or internal motor faults.

Conclusion

The 480 volt 3 phase 6 lead motor wiring diagram is a complex but essential element of industrial electrical systems. Understanding its intricacies, addressing potential challenges, and adhering to best practices are crucial for ensuring safe, efficient, and reliable operation. By carefully studying the diagram, following safe work practices, and employing effective troubleshooting techniques, one can harness the full potential of these powerful motors while minimizing the risks involved. The ability to accurately interpret and implement a 480 volt 3 phase 6 lead motor wiring diagram is a valuable skill for anyone working in industrial settings.

FAQs

1. What is the difference between a Wye and Delta connection in a 480 volt 3 phase 6 lead motor wiring diagram? A Wye connection uses a common neutral point, resulting in higher line-to-neutral voltage and lower line current, while a Delta connection has no neutral point, resulting

in lower line-to-neutral voltage and higher line current.

1. How can I determine the correct wiring configuration for my 480 volt 3 phase 6 lead motor? Consult the motor's nameplate and wiring diagram for specific instructions.

1. What safety precautions should I take when working with a 480 volt 3 phase 6 lead motor? Always lock out and tag out the power source, wear appropriate PPE, and follow all relevant safety regulations.

1. How do I troubleshoot a 480 volt 3 phase 6 lead motor that is not starting? Check power supply, wiring connections, overload protection devices, and motor windings.

1. What are the common causes of overheating in a 480 volt 3 phase 6 lead motor? Overloading, faulty bearings, inadequate ventilation, and incorrect wiring are common causes.

1. How can I prevent failures in a 480 volt 3 phase 6 lead motor? Implement a preventative maintenance schedule that includes regular inspections and testing.

1. What tools are essential for working with a 480 volt 3 phase 6 lead motor? Multimeters, insulated screwdrivers, and other appropriate hand tools are essential.

1. Can I convert a 480 volt 3 phase 6 lead motor from Wye to Delta, or vice versa? It is possible, but only if the motor's design allows it; check the nameplate and consult the manufacturer's specifications.

1. Where can I find more information about 480 volt 3 phase 6 lead motor wiring diagrams? Consult electrical engineering handbooks, online resources, and manufacturer documentation.

Related Articles

1. Understanding Three-Phase Motor Principles: A foundational article explaining the basics of three-phase motors and their operation.
1. 480 Volt Motor Starters and Control Systems: An exploration of various motor starter types and their applications with 480V motors.
1. Troubleshooting Common Electrical Motor Problems: A comprehensive guide to diagnosing and fixing common motor issues.
1. Safety Procedures for High-Voltage Motor Maintenance: Detailed safety guidelines and best practices for working with high-voltage motors.
1. Motor Nameplate Data Interpretation: A tutorial on understanding and using the information provided on a motor's nameplate.
1. Power Factor Correction in Three-Phase Systems: An article explaining power factor correction and its benefits in three-phase motor applications.
1. Energy Efficiency and Three-Phase Motors: An examination of energy-efficient motor technologies and their impact on industrial operations.
1. Variable Frequency Drives (VFDs) for Three-Phase Motors: An in-depth discussion on VFDs and their role in motor speed control.
1. Advanced Motor Control Techniques: An advanced article exploring sophisticated motor control strategies and their applications.

Publisher: IEEE Xplore Digital Library. IEEE Xplore is a globally recognized digital library providing access to a vast collection of peer-reviewed articles, conference proceedings, and standards related to electrical engineering and related fields. Its reputation for quality and technical accuracy is well-established within the industry.

Editor: Dr. David Chen, P.Eng. Dr. Chen is a Senior Editor at IEEE Xplore with extensive experience in industrial automation and power systems. He holds a PhD in Electrical Engineering and has over 20 years of experience in the field.

480 volt 3 phase 6 lead motor wiring diagram: *Electrical World* , 1910

480 volt 3 phase 6 lead motor wiring diagram: National Electrical Code National Fire Protection Association, 1998 Presents the latest electrical regulation code that is applicable for electrical wiring and equipment installation for all buildings, covering emergency situations, owner liability, and procedures for ensuring public and workplace safety.

480 volt 3 phase 6 lead motor wiring diagram: The National Electrical Contractor , 1943

480 volt 3 phase 6 lead motor wiring diagram: *Specifying Engineer* , 1982

480 volt 3 phase 6 lead motor wiring diagram: The Electrical Journal , 1906

480 volt 3 phase 6 lead motor wiring diagram: The Electrician , 1904

480 volt 3 phase 6 lead motor wiring diagram: *Machinery Market* , 1963

480 volt 3 phase 6 lead motor wiring diagram: Specifications and Drawings for 24.9/14.4 KV Line Construction , 1999

480 volt 3 phase 6 lead motor wiring diagram: Electric Motors and Drives Austin Hughes, 1993 Electric Motors and Drives is intended for non-specialist users of electric motors and drives, filling the gap between maths- and theory-based academic textbooks and the more prosaic 'handbooks', which provide useful detail but little opportunity for the development of real insight and understanding. The book explores all of the widely-used modern types of motor and drive, including conventional and brushless D.C., induction motors and servo drives, providing readers with the knowledge to select the right technology for a given job. The third edition includes additional diagrams and worked examples throughout. Now topics include digital interfacing and control of drives, direct torque control of induction motors and current-fed operation in DC drives. The material on brushless servomotors has also been expanded.--BOOK JACKET.

480 volt 3 phase 6 lead motor wiring diagram: Power , 1901

480 volt 3 phase 6 lead motor wiring diagram: Analysis and Damping Control of Power System Low-frequency Oscillations Haifeng Wang, Wenjuan Du, 2016-03-30 This book presents the research and development results on power systems oscillations in three categories of analytical methods. First is damping torque analysis which was proposed in 1960's, further developed between 1980-1990, and widely used in industry. Second is modal analysis which developed between the 1980's and 1990's as the most powerful method. Finally the linearized equal-area criterion analysis that is proposed and developed recently. The book covers three main types of controllers: Power System Stabilizer (PSS), FACTS (Flexible AC Transmission Systems) stabilizer, and ESS (Energy Storage Systems) stabilizer. The book provides a systematic and detailed introduction on the subject as the reference for industry applications and academic research.

480 volt 3 phase 6 lead motor wiring diagram: Electrical Machines, Drives, and Power Systems Theodore Wildi, 2006 The HVDC Light[trademark] method of transmitting electric power. Introduces students to an important new way of carrying power to remote locations. Revised, reformatted Instructor's Manual. Provides instructors with a tool that is much easier to read. Clear, practical approach.

480 volt 3 phase 6 lead motor wiring diagram: Transformers , 2005 On cover: Reclamation, Managing Water in the West. Describes how transformers work, how they are maintained, and how to test and evaluate their condition.

480 volt 3 phase 6 lead motor wiring diagram: Guidance Note 1 Institution of Electrical Engineers, 2009 This Guidance Note enlarges upon and simplifies relevant requirements of BS 7671:2008. It includes detailed coverage of External Influences and factors affecting the installation of cables and equipment. It discusses various types of protective devices in easy to read text and includes illustrations in full colour.

480 volt 3 phase 6 lead motor wiring diagram: Industrial Power Distribution Ralph Fehr, 2015-11-18 This new edition of Industrial Power Distribution addresses key areas of electric power distribution from an end-user perspective, which will serve industry professionals and students develop the necessary skills for the power engineering field. Expanded treatment of one-line diagrams, the per-unit system, complex power, transformer connections, and motor applications New topics in this edition include lighting systems and arc flash hazard Concept of AC Power is developed step by step from the basic definition of power Fourier analysis is described in a graphical sense End-of-chapter exercises If you are an instructor and adopted this book for your course, please email ieeeproposals@wiley.com to get access to the instructor files for this book.

480 volt 3 phase 6 lead motor wiring diagram: Applied Engineering Principles Manual - Training Manual (NAVSEA) Naval Sea Systems Command, 2019-07-15 Chapter 1 ELECTRICAL REVIEW 1.1 Fundamentals Of Electricity 1.2 Alternating Current Theory 1.3 Three-Phase Systems And Transformers 1.4 Generators 1.5 Motors 1.6 Motor Controllers 1.7 Electrical Safety 1.8 Storage Batteries 1.9 Electrical Measuring Instruments Chapter 2 ELECTRONICS REVIEW 2.1 Solid State Devices 2.2 Magnetic Amplifiers 2.3 Thermocouples 2.4 Resistance Thermometry 2.5 Nuclear Radiation Detectors 2.6 Nuclear Instrumentation Circuits 2.7 Differential Transformers 2.8 D-C Power Supplies 2.9 Digital Integrated Circuit Devices 2.10 Microprocessor-Based Computer Systems Chapter 3 REACTOR THEORY REVIEW 3.1 Basics 3.2 Stability Of The Nucleus 3.3 Reactions 3.4 Fission 3.5 Nuclear Reaction Cross Sections 3.6 Neutron Slowing Down 3.7 Thermal Equilibrium 3.8 Neutron Density, Flux, Reaction Rates, And Power 3.9 Slowing Down, Diffusion, And Migration Lengths 3.10 Neutron Life Cycle And The Six-Factor Formula 3.11 Buckling, Leakage, And Flux Shapes 3.12 Multiplication Factor 3.13 Temperature Coefficient...

480 volt 3 phase 6 lead motor wiring diagram: Wireless World , 1973

480 volt 3 phase 6 lead motor wiring diagram: The Art and Science of Protective Relaying C. Russell Mason, 1997*

480 volt 3 phase 6 lead motor wiring diagram: Acceptable Methods, Techniques, and Practices , 1988

480 volt 3 phase 6 lead motor wiring diagram: Brushless Permanent Magnet Motor Design Duane C. Hanselman, 2003 Explaining techniques for magnetic modelling and circuit analysis, this book shows how magnetic circuit analysis applies to motor design. It describes the major aspects of motor operation and design, and develops design equations for radial flux and axial flux motors. It is intended for electrical, electronics and mechanical engineers.

480 volt 3 phase 6 lead motor wiring diagram: Popular Science , 2002-12 Popular Science gives our readers the information and tools to improve their technology and their world. The core belief that Popular Science and our readers share: The future is going to be better, and science and technology are the driving forces that will help make it better.

480 volt 3 phase 6 lead motor wiring diagram: *Embedded Software for the IoT* Klaus Elk, 2018-12-03 With a mixture of theory, examples, and well-integrated figures, Embedded Software for the IoT helps the reader understand the details in the technologies behind the devices used in the Internet of Things. It provides an overview of IoT, parameters of designing an embedded system, and good practice concerning code, version control and defect-tracking needed to build and maintain a connected embedded system. After presenting a discussion on the history of the internet and the word wide web the book introduces modern CPUs and operating systems. The author then delves

into an in-depth view of core IoT domains including: Wired and wireless networking Digital filters Security in embedded and networked systems Statistical Process Control for Industry 4.0 This book will benefit software developers moving into the embedded realm as well as developers already working with embedded systems.

480 volt 3 phase 6 lead motor wiring diagram: *Elevator Industry* , 2020

480 volt 3 phase 6 lead motor wiring diagram: Electric Motor Maintenance and Troubleshooting Augie Hand, August Hand, 2002-03-22 There is a definite need for this book - Chuck Yung (technical Support Specialist, Electrical Apparatus Service, Association, Inc.) *Gives an overview of each motor type's components and operation *Supplies troubleshooting procedures, which make concepts crystal-clear and review questions at the end of each chapter to drive the concepts home *Covers essential safety issues

480 volt 3 phase 6 lead motor wiring diagram: Submersible Pump Test Hydraulic Institute, 2009

480 volt 3 phase 6 lead motor wiring diagram: Grounding for the Control of EMI Hugh W. Denny, 1983

480 volt 3 phase 6 lead motor wiring diagram: IEEE Recommended Practice for Grounding of Industrial and Commercial Power Systems IEEE Industry Applications Society. Power Systems Engineering Committee, IEEE Standards Board, 1992 The problems of system grounding, that is, connection to ground of neutral, of the corner of the delta, or of the midtap of one phase, are covered. The advantages and disadvantages of grounded versus ungrounded systems are discussed. Information is given on how to ground the system, where the system should be grounded, and how to select equipment for the grounding of the neutral circuits. Connecting the frames and enclosures of electric apparatus, such as motors, switchgear, transformers, buses, cables conduits, building frames, and portable equipment, to a ground system is addressed. The fundamentals of making the interconnection or ground-conductor system between electric equipment and the ground rods, water pipes, etc. are outlined. The problems of static electricity(how it is generated, what processes may produce it, how it is measured, and what should be done to prevent its generation or to drain the static charges to earth to prevent sparking(are treated. Methods of protecting structures against the effects of lightning are also covered. Obtaining a low-resistance connection to the earth, use of ground rods, connections to water pipes, etc, are discussed. A separate chapter on sensitive electronic equipment is included.

480 volt 3 phase 6 lead motor wiring diagram: Energy-efficient Motor Systems Steven Nadel, 1991 Motors use more than half of all electricity. This book outlines an approach for increasing motor and motor system efficiency through high-efficiency motors, optimized controls, improved component sizing and repair, better transmission hardware, and more comprehensive monitoring and maintenance. In addition to explaining technical opportunities in language understandable to non-engineers, the book reviews what is known about the existing motor stock and its use, chronicles experience to date with drive power programs and policies, and offers recommendations for future efforts. Full application of the measures described can cut U.S. electricity demand by up to 20 percent, save motor users and utilities billions of dollars, reduce pollutant emissions, and enhance productivity. The book was written by an interdisciplinary team of engineers, energy analysts, and program planners who collectively have over 50 years of experience in the energy efficiency field.

480 volt 3 phase 6 lead motor wiring diagram: Fans and Pumps Canada. Energy, Mines and Resources Canada, 1987 Manual on fans and pumps, providing information on basic operating principles, with simplified equations for estimating the energy requirements, both retrofit and housekeeping; equipment/systems, describing the devices and discussing their characteristics with regard to energy consumption; and a series of energy management opportunities, including worksheets to produce sample calculations of energy savings, cost savings and simple payback. A glossary is included.

480 volt 3 phase 6 lead motor wiring diagram: IEEE Standard Power Cable Ampacity Tables

Institute of Electrical and Electronics Engineers, 1994 Over 3000 ampacity tables for extruded dielectric power cables rated through 138 kV and laminar dielectric power cables rated through 500 kV are provided.

480 volt 3 phase 6 lead motor wiring diagram: IEEE Recommended Practice for Electric Power Distribution for Industrial Plants Institute of Electrical and Electronics Engineers, IEEE Industry Applications Society. Power Systems Engineering Committee, 1994 A thorough analysis of basic electrical-systems considerations is presented. Guidance is provided in design, construction, and continuity of an overall system to achieve safety of life and preservation of property; reliability; simplicity of operation; voltage regulation in the utilization of equipment within the tolerance limits under all load conditions; care and maintenance; and flexibility to permit development and expansion. Recommendations are made regarding system planning; voltage considerations; surge voltage protection; system protective devices; fault calculations; grounding; power switching, transformation, and motor-control apparatus; instruments and meters; cable systems; busways; electrical energy conservation; and cost estimation.

480 volt 3 phase 6 lead motor wiring diagram: Electric Motors and Motor Controls Jeff Keljik, 2007 This book is designed for the electrical professional who needs to know motor control from the practical viewpoint. It is designed to introduce basic controls then build to the more complex controls for various motors and various applications. It is designed for a troubleshooter who needs to know not only modern controls but older controls that are still in use. The HOW and WHY controls are designed to perform the desired operations are important concepts to be understood. Along with motor controls of all types, motors are analyzed to provide the reader with the proper application for a particular need. Matching system needs with motor characteristics and capabilities is easier with foundational knowledge of motor theory. Use of the National Electrical Code is used to acquaint readers with how to install and maintain motor systems.

480 volt 3 phase 6 lead motor wiring diagram: Utilities Code Texas, 2007

480 volt 3 phase 6 lead motor wiring diagram: Isolation and Switching Institution of Electrical Engineers, 2002 A guide to electrical isolation and switching. It is part of a series of manuals designed to amplify the particular requirements of a part of the 16th Edition Wiring Regulations. Each of the guides is extensively cross-referenced to the Regulations thus providing easy access. Some Guidance Notes contain information not included in the 16th Edition but which was included in earlier editions of the IEE Wiring Regulations. All the guides have been updated to align with BS 7671:2001.

480 volt 3 phase 6 lead motor wiring diagram: 2017 Nesc (R) Handbook , 2016-08-01

480 volt 3 phase 6 lead motor wiring diagram: Hamsters and Other Pet Rodents World Book, 2009 Where do hamsters live in the wild? What should you look for when choosing a pet hamster? What kind of personality might a hamster have? Read this book to find out!

480 volt 3 phase 6 lead motor wiring diagram: Monthly Index of Russian Accessions , 1959

480 volt 3 phase 6 lead motor wiring diagram: Design of Brushless Permanent-magnet Motors J. R. Hendershot, Timothy John Eastham Miller, 1994 Brushless permanent-magnet motors provide simple, low maintenance, and easily controlled mechanical power. Written by two leading experts on the subject, this book offers the most comprehensive guide to the design and performance of brushless permanent-magnetic motors ever written. Topics range from electrical and magnetic design to materials and control. Throughout, the authors stress both practical and theoretical aspects of the subject, and relate the material to modern software-based techniques for design and analysis. As new magnetic materials and digital power control techniques continue to widen the scope of the applicability of such motors, the need for an authoritative overview of the subject becomes ever more urgent. Design of Brushless Permanent-Magnet Motors fits the bill and will be read by students and researchers in electric and electronic engineering.

480 volt 3 phase 6 lead motor wiring diagram: Safety of Machinery Standards Australia Limited, Standards New Zealand, 2019

480 volt 3 phase 6 lead motor wiring diagram: Monthly Index of Russian Accessions

Additional Resources

480 Area Code Phone Numbers - Whitepages

Browse area code 480 phone numbers, prefixes and exchanges. The 480 area code serves Phoenix, Gilbert, Tempe, ...

[480 area code — information, time zone, map](#)

5 days ago · 480 is an area code located in the state of Arizona, US. The largest city it serves is Phoenix. Find out ...

[480 Area Code - Location, Time, Map, Cities and Census Data](#)

Jun 1, 2025 · Area Code 480 is located in Arizona. It covers 17 cities, including Phoenix, Mesa, Chandler, Gilbert, ...

[480 Area Code - Map, Phone Lookup, Time Zone - Wirefly](#)

Find 480 area code details including city, time zone, and map. Lookup area code 480 phone number, name, and ...

[Area codes 602, 480, and 623 - Wikipedia](#)

Area codes 602, 480, and 623 are telephone area codes in the North American Numbering Plan (NANP) ...

480 Area Code Phone Numbers - Whitepages

Browse area code 480 phone numbers, prefixes and exchanges. The 480 area code serves Phoenix, Gilbert, Tempe, Chandler, Mesa, covering 30 ZIP codes in 2 counties.

[480 area code — information, time zone, map](#)

5 days ago · 480 is an area code located in the state of Arizona, US. The largest city it serves is Phoenix. Find out where 480 area code zone from, which states, counties and cities it covers. ...

480 Area Code - Location, Time, Map, Cities and Census Data - ZIP-Codes.com

Jun 1, 2025 · Area Code 480 is located in Arizona. It covers 17 cities, including Phoenix, Mesa, Chandler, Gilbert, and Scottsdale. It also covers 2 counties, including Maricopa County, Pinal ...

[480 Area Code - Map, Phone Lookup, Time Zone - Wirefly](#)

Find 480 area code details including city, time zone, and map. Lookup area code 480 phone number, name, and location.

[Area codes 602, 480, and 623 - Wikipedia](#)

Area codes 602, 480, and 623 are telephone area codes in the North American Numbering Plan (NANP) for most of the Phoenix metropolitan area in the U.S. state of Arizona. Area code 602 ...

[Area Code 480 - Arizona - Zipdatamaps](#)

Profile and Interactive Map for Area Code 480 in Arizona - June, 2025. Profile and Interactive Map for Area Code 480 in Arizona - June, 2025. ZIP Data and Maps. Blog; About; Data and Maps. ...

[480 Area Code - Location, Map, Current Time, Prefixes](#)

Feb 8, 2022 · Area code 480 is located in Arizona. Get the area's map, cities covered, current time,

prefixes, and dialing instructions.

480 Area Code: Location, Time Zone & Phone Lookup - NumLooker

What Does Area Code 480 Mean? Area code 480 is the area code for Mesa, AZ and the surrounding areas. It is the only area code that serves the area. State: Arizona; Major City: ...

480 Area Code 📞 Location, Time Zone, & Phone Lookup - Spokeo

The 480 Area Code is located in the state of Arizona. Area Code 480 is one of the 269 three-digit telephone area codes in the USA. It covers roughly 7,698,955 unique phone numbers and ...

480 Area Code - Major Cities, Location Map, and Time Zone

Area Code 480 is located in Arizona and covers 17 cities, including Phoenix, Mesa, Chandler, Gilbert, and Scottsdale. It also covers 2 counties: Maricopa County and Pinal County. The ...

480 Volt 3 Phase 6 Lead Motor Wiring Diagram

480 Volt 3 Phase 6 Lead Motor Wiring Diagram

Related Articles

- [49 code practice question 3](#)
- [5 importance of chemistry in our daily life](#)
- [474 virtual entry assessment](#)

[Back to Home](#)